

A.22.8 Wood Stop @ Window
FULL SCALE



A.22.6 Cast Stone Cap
N.T.S.



A.22.7 Window Sill
3"=1'-0"



A.22.4 Door Jamb
3"=1'-0"



A.22.5 Astragal
FULL SCALE



A.22.2 Door Detail
FULL SCALE



A.22.3 Shutter Detail
3"=1'-0"



A.22.1 Second Floor Plan
1/4"=1'
2064 sf gross interior

Kampmann House
Second Floor

Bldg #235 142 Goliad Rd.
Ca. 1878

KEYNOTES

1. RELOCATE DOORS TO SWING IN / USE EXISTING STOPS
2. REMOVE OUTER STOPS / STRIP WOOD PANELS AND PAINT SIMILAR TO LEVEL 1
3. NEW SASH LOCK
4. RAISE UPPER SASH AND SECURE
5. NEW WOOD SILL / SEE A.22.7
6. REPLACE SASH CORD AND SECURE TO EXISTING WEIGHT
7. SECURE WOOD STOPS
8. CLEAN GLAZING
9. REPAIR LATCH BOLT MECHANISM
10. CLEAN TOILET FIXTURES / SEE ALSO MEP
11. NO WORK IN THESE TOILET ROOMS
12. REPLACE METAL SASH CORD
13. EXISTING WINDOW FRAME AND TRIM
14. NEW WOOD STOP / SEE A.22.8 FOR PROFILE
15. NEW FIXED BLADE SHUTTERS / SEE A.40.9 FOR CONSTRUCTION
16. DECORATIVE MOLDING / MATCH EXISTING
17. GYPSUM BOARD ON WOOD STUDS
18. 3/4 x 3 TRIM WITH OGEE PROFILE / TYPICAL AT DOOR OPENING AND BASE IN TOILET ROOM
19. 3/4 x 5-1/2 TRIM WITH OGEE PROFILE
20. DOOR STOP / MATCH PROFILE OF EXISTING
21. DOOR
22. NEW CAST STONE CAP
23. EXISTING STONE WALL / REPOINT
24. SEALANT
25. STONE SILL
26. NEW HARDBOARD OVERLAYMENT ON WOOD FLOORING

project no. 9[illegible]

date OCT 1991

HEMISFAIR PARK
HISTORIC STRUCTURES – PHASE II
CITY OF SAN ANTONIO

Rehler Vaughn Beals & Koone, Inc.
architecture
interior architecture
landscape architecture
master planning

RVBK
ARCHITECTS
A.22