


# Cathedral Rock Park



**LEGEND**

- Bridge
- Parking
- Restroom
- Park Entrance
- Playground
- River/Creek
- Road

**A Trail Access Information**  
*Typical Trail Qualities*

Trail Name	Length	Typical Grade	Maximum Grade Standard Ramp is 8.3%	Typical Cross Slope	Maximum Cross Slope	Typical Tread Width	Minimum Clearance Width	Surface Type
Culebra Creek Trail	443 ft	2.0%	53 ft is 6% - 8.3%	2.0%	90 ft is 4% - 5%	72 in	72 in	Crushed Stone (Fines)
Loop Trail	176 ft	2.4%	100% is < 5%	1.1%	25 ft is 3%	90 in	72 in	Concrete
Ammonite Trail	341 ft	7.9%	137 ft is 9% - 16%	4.3%	125 ft is 6% - 15%	60 in	60 in	Soil
Prickly Pear Pass	205 ft	2.1%	100% is < 5%	2.0%	26 ft is 6%	72 in	72 in	Crushed Stone (Fines)
Wash Tub Pass	199 ft	2.8%	45 ft is 6% - 8.3%	2.2%	50 ft is 4% - 5%	72 in	72 in	Crushed Stone (Fines)
Bluffs Trail	442 ft	3.4%	16 ft is 12%	2.4%	74 ft is 6% - 7%	60 in	60 in	Crushed Stone (Fines)
Yucca Pass	144 ft	3.8%	27 ft is 6% - 8.3%	1.7%	29 ft is 4% - 5%	72 in	72 in	Crushed Stone (Fines)
Cathedral Rock Trail	0.4 mi	2.9%	68 ft is 9% - 11%	2.0%	120 ft is 6% - 9%	72 in	72 in	Crushed Stone (Fines)
Leon Creek Greenway Connector Trail	0.9 mi	2.4%	98 ft is 9% - 15%	1.5%	0.2 mi is 3% - 5%	96 in	96 in	Concrete
Owl's Nest Trail	374 ft	4.1%	50 ft is 12% - 18%	4.3%	104 ft is 6% - 14%	60 in	60 in	Crushed Stone (Fines)

**Balance** Find your METRO HEALTH SAN ANTONIO PUBLIC HEALTH TEAM  
**FDR** **WARNING:** Trail conditions may have changed since March 2011 when these trails were assessed. Signage created by Beneficial Designs Inc. using trail data collected by a certified trail assessment contractor.

